

Oceanworks

2703 TENTH St
Berkeley, CA 94710
510-849-1383


Email: oceanworksberkeley@gmail.com
Website: AskAngus.com
BAR License Number: 294835

Invoice

Bill To Cakici, Basak



Mobile



Invoice # 6210
Work Order # 7679
Service Advisor Chris Cucuel
Technician Rich Ikeda

Plate CA 6BHP185
Description 2007 Toyota Prius Base L4 1.5L 1497CC
VIN JTDKB20U973295562
Odometer 145,167
Invoice Date 7/21/2021 1:46 PM
Appointment 7/21/2021 7:50 AM
Promised 7/21/2021 5:00 PM

Service

Pre Scan Computer Engine Controls Concern HAT - 697

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor

\$80.00

Sub \$80.00

Stolen Catalytic Converter (Prius GEN 2)

Inspect, diagnose, file insurance claim with pictures if needed, remove damaged components and replace need

17410-21500 - Catalytic Converter	1 Unit	\$2,436.97 / Unit	\$2,436.97 S
17451-21060 - EXHAUST GASKET	1 Unit	\$62.81 / Unit	\$62.81 S
17451-23010 - EXHAUST GASKET	1 Unit	\$27.24 / Unit	\$27.24 S
90501-A0031 - SPRING	2 Unit	\$5.75 / Unit	\$11.50 S
90501-A0031 - SPRING	2 Unit	\$5.75 / Unit	\$11.50 S
90080-10291 - BOLT	2 Unit	\$11.81 / Unit	\$23.62 S
90109-05026 - BOLT	2 Unit	\$5.34 / Unit	\$10.68 S

Labor

\$176.00

Sub \$2,760.32

Catalytic Converter Cage Prius (2005 - 2009)

Description

002X002W0630W48T - MESH 063 G, PER FOOT	4 Unit	\$49.10 / Unit	\$196.40 S
123.02.12.1 - SELF DRILLING SCREW	18 Unit	\$0.75 / Unit	\$13.50 S
412.01.316.01 - WASHER	18 Unit	\$0.75 / Unit	\$13.50 S

Labor

\$240.00

Sub \$463.40

Oxygen Sensor(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

89465-47070 - Oxygen Sensor	1 Unit	\$184.99 / Unit	\$184.99 S
-----------------------------	--------	-----------------	------------

Labor

\$64.00

Sub \$248.99

The COVID-19 (Coronavirus) outbreak is an ongoing, rapidly developing situation. Oceanworks is meeting and exceeding the Centers for Disease Control guidelines while working in and around your vehicle. All vehicles are disinfected with a Chlorine Dioxide solution applied with a positive ionized sprayer that kills 99.8% of a number of virus and bacteria including COVID-19. Seat, steering wheel and shifter covers are utilized as well. Technicians wear gloves and masks while working on your car.

Scan Computer Engine Controls Concern

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor

\$80.00

Sub \$80.00

Total Parts

\$2,992.71

Total Labor

\$640.00

Total Before Taxes & Miscellaneous Charges

\$3,632.71

(S) State Sales Tax

10.25 %

\$306.75

Grand Total

\$3,939.46

CAKICI/BASAK paid \$3,939.46 by [REDACTED]

7/21/2021 1:46 PM [REDACTED] Entry Method: Chip Type: Sale Amount: 3939.46

Terminal: 28099 Transaction: 0d94f4f3-228b-4332-9cb8-c1c4c991a938 Authorization: 37026D Result: Approved

AID: A0000000031010 TC: E79FE6A29AB3660D TVR: 8000008000 TSI: 6800 ATC: 026C ARC: Z3

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.



Invoice Signature. Signed on 7/21/2021 1:46 PM

Thanks for the Business!

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____

The COVID-19 (Coronavirus) outbreak is an ongoing, rapidly developing situation. Oceanworks is meeting and exceeding the Centers for Disease Control guidelines while working in and around your vehicle. All vehicles are disinfected with a Chlorine Dioxide solution applied with a positive ionized sprayer that kills 99.8% of a number of virus and bacteria including COVID-19. Seat, steering wheel and shifter covers are utilized as well. Technicians wear gloves and masks while working on your car.