



**Sunset Auto Care**  
 3865 Irving Street  
 San Francisco, CA 94122  
 (415) 664-1735  
 service@sunsetauto.shop  
 http://www.sunsetauto.shop

**Invoice for RO #2124**

Service Advisor: Isaiah Zazi  
 Date Created: 02/11/25 at 09:34 AM PST  
 Client: Pierre Martin  
 Vehicle: 2018 Volkswagen Tiguan SE

Pierre Martin Phone: (415) 685-1131	2018 Volkswagen Tiguan SE 2.0L 4Cyl GAS DGUA Turbocharged VIN: 3VV3B7AX2JM166595 License: 8XUG872 Color: N/A Odometer In: 90680 / Out: 90682	RO # 2124 Time-In: 02/11/25 at 09:34 AM PST Save Parts: No
--	---	--

<b>1 - Remove &amp; Replace Engine Oil Pressure Sensor/Switch</b>		
Labor:	Remove & Replace Engine Oil Pressure Sensor/Switch Primary	\$228.00
Part:	FAE Oil Pressure Sender - 06K 919 081	1 \$39.98
✓ Approved on 02/12/25 at 02:05 PM PST		Subtotal \$267.98 + est. Tax \$3.45 <b>\$271.43</b>

Sunset Auto Care is not responsible for any damage or loss that may occur to your vehicle or its contents during or after the repair service, especially when parked on the lot overnight. By agreeing to use our services, you acknowledge that you have read and understand this disclaimer and agree to release Sunset Auto Care from any liability for damages or losses.

**Total Repair Order & Signature:**

Total Jobs: \$267.98  
 Total Fees: \$0.00  
**Subtotal: \$267.98**  
 Taxes: \$3.45  
**Grand Total: \$271.43**  
**BALANCE DUE: \$271.43**

X

-----



**SUNSET AUTO CARE**  
 3865 IRVING STREET  
 SAN FRANCISCO, CA 94122  
 4156641735  
 WWW.SUNSETAUTO.SHOP

Transaction 000428

**Total \$279.57**  
 DEBIT CARD SALE \$279.57  
 VISA 2174

Retain this copy for statement validation

12-Feb-2025 3:55:46P  
 \$279.57 | Method: CONTACTLESS  
 US DEBIT XXXXXXXXXXXX2174  
 VISA CARDHOLDER  
 Reference ID: 504300507284  
 Auth ID: 001487  
 MID: \*\*\*\*\*5883  
 AID: A000000980840  
 AuthNwkn: MAESTRO  
 Rlnnd: DEBIT  
 PIN VERIFIED

\*\*\* REPRINT \*\*\*

Payment T1F2CTAWDXVE  
 Clover Privacy Policy  
<https://clover.com/privacy>