

XYZ Motors

299 29th Street
Oakland, CA 94611-5704
Ph: (510) 835-8882
xyzmotors@gmail.com

Repair Order #1918

Service Writer: A
Created: 03/17/25 09:20 AM
Updated: 03/19/25 10:22 AM

Brian Baker (Authorizer)
M: (415) 867-4006

2007 Lincoln MKX

V6-3.5L DOHC 24v MFI VIN C GAS
VIN: 2LMDU88CX7BJ15958
License Plate: 5ZKC393 CA

Mileage: In 168071 | Out
168071

"We are committed to making your car ownership a pleasant experience"

ITEM	DESCRIPTION	PART #	QTY/HRS	PRICE/RATE	TOTAL
Spray Nozzle Replacement					120.00
Labor	-Customer states washer fluid does not spray fluid. -Inspected windshield washer system = *Found left washer fluid spray nozzle is broken. *Recommend replacement of left spray nozzle, then reinspect. -Notified customer of findings - Customer approved repairs. -Replaced left windshield washer spray nozzle. -Tested windshield washer system to verify repairs.	Labor	0.50	160.00	80.00
Part	Spray Nozzle		1	40.00	40.00
Oil Leak Inspection					160.00
Labor	-Customer requested oil leak inspection. -Findings: *Large leak from valve cover gaskets, possible timing cover gasket is also leaking. *Seepage from oil pan gasket. *Minor leak from power steering rack and pinion. *Moderate leak from rear differential cover. *Recommend replacement of valve cover gasket and rear differential cover, then reinspect. -Notified customer of findings - Customer approved repairs.	Labor	1.00	160.00	160.00
Valve Cover Gasket Replacement					700.00
Labor	Replaced valve cover gasket set. Replaced spark plug tube seals. Replaced VVT Solenoid seal. Replaced upper intake manifold gasket. Cleaned engine of residual oil. Road tested vehicle to verify repairs.	Custom Labor Rate	3.40	160.00	544.00
Part	Valve Cover Gasket Set		1	105.00	105.00
Part	VVT Solenoid Seal		2	10.00	20.00
Part	Intake Manifold Gasket - Upper		1	31.00	31.00
Rear Differential Cover Replacement					300.00
Labor	-Drained existing differential -Resealed rear differential cover. -Refilled rear differential fluid to capacity. -Cleaned surrounding areas of oil residue. -Road tested vehicle to verify repairs.	Labor	1.47	160.00	235.20
Part	Silicone Sealant		1	12.30	12.30
Part	80W-90 Premium Gear Oil		1.5	35.00	52.50
Drive Belt Replacement					160.00
Labor	Replaced serpentine drive belt	Custom Labor Rate	0.60	160.00	96.00
Part	Serpentine Drive Belt		1	64.00	64.00

XYZ Motors
Ph: (510) 835-8882 • xyzmotors@gmail.com
Brian Baker
2007 Lincoln MKX V6-3.5L DOHC 24v MFI VIN C GAS

Repair Order #1918
Service Writer: A
Updated: 03/19/25 10:22 AM

Authorizer	Date	Authorization Method	Shop Representative	Add. Amount	Total
Deposits:				Parts:	\$324.80
No Deposits recorded				Labor:	\$1115.20
				Shop Supplies:	\$0.00
				HazMat:	\$3.00
				Subtotal:	\$1443.00
				Total Tax:	\$33.29
X _____				Revised Total: \$1476.29	
Customer Signature				Deposits -\$0.00	
Date 03-19-2025					

XYZ Motors
Ph: (510) 835-8882 • xyzmotors@gmail.com
Brian Baker
2007 Lincoln MKX V6-3.5L DOHC 24v MFI VIN C GAS

Repair Order #1918
Service Writer: A
Updated: 03/19/25 10:22 AM

Authorizer	Date	Authorization Method	Shop Representative	Add. Amount	Total
Deposits:				Parts:	\$324.80
No Deposits recorded				Labor:	\$1115.20
				Shop Supplies:	\$0.00
				HazMat:	\$3.00
				Subtotal:	\$1443.00
				Total Tax:	\$33.29
X _____				Revised Total: \$1476.29	
Customer Signature				Deposits -\$0.00	
Date 03-19-2025					