

Vehicle Labor and Part History

Bavarian Professionals, Inc.

MH 5/08/2025

Customer: Julian Dodd

Vehicle: 2011 BMW X5 35dX L6 3.0L, 2993cc, DOHC, DIESEL, FI

VIN: L657809

Unit/Fleet Num:

Phone: 415-756-3981

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
114842	4/29/2025	0	NS	4/29/2025		Total:	0.00
Parts Only							
LABOR: Parts only:							0.00
64-55-7-809-801	4kx843 belt E70 M57 A/C					-1.00	-34.26
11-28-7-631-822	4kx843 belt					1.00	34.26
114794	4/24/2025	199,076	MH	4/24/2025		Total:	907.07
Screeching sounds when accel							
LABOR: Test drive with owner: some noise heard from front of engine briefly.					1.00	2.25	540.00
Inspect drive belts: worn (replaced 7/21 at 127k miles). Remove & replace drive belts belt tensioner pulleys. Note: slight squeal heard on test drive: boos leak or turbo suspect.							
Additional 3-4h needed for diagnosis.							
11-28-7-803-476	6kx1893 belt					1.00	52.50
11-28-7-799-851	Pulley idler					1.00	169.61
64-55-7-809-801	4kx843 belt E70 M57 A/C					1.00	34.26
11-28-8-585-243	Pulley					1.00	76.57
Check tire pressures. Adjust to recommended pressures.							
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.							0.00
Front 32psi							
Rear 36psi							
Check Condition-Based Service menu for overdue or upcoming services, note due date/remaining mileage. Measure brakes if <5000 miles remaining.							
Vehicle check 3400 or 3/28							
Oil & filter 6k or 1/27							
Brake fluid flush 7/25							
F brakes 27k							
R brakes 20k							
Loaner car							
LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO9, and agrees to terms of Loaner Car Agreement as shown on reverse.							0.00
114541	3/27/2025	0	MH	3/27/2025		Total:	267.91
Remote intermittent							
LABOR: Parts only:							0.00
66-12-6-986-583	Master remote w/o CA					1.00	243.00
113700	1/13/2025	193,680	MH	1/13/2025		Total:	386.83
Oil & filter change							
LABOR: Drain & replace engine oil, remove & replace oil filter. Reset CBS if less than 5,000 miles or 12 months remaining. Top up diesel exhaust fluid, note quantity used.					0.75		150.00
83-21-5-A2A-F87	Oil BMW 5W30 diesel, lite					7.50	112.95
11-42-7-788-460	Oil filter kit M57					1.00	24.40
83-19-0-440-158 QT	Exhaust fluid diesel, qua					14.00	56.70

Vehicle Labor and Part History

Bavarian Professionals, Inc.

MH 5/08/2025

Customer: Julian Dodd

Vehicle: 2011 BMW X5 35dX L6 3.0L, 2993cc, DOHC, DIESEL, FI

VIN: L657809

Unit/Fleet Num:

Phone: 415-756-3981

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system. Front 32psi Rear 36psi							0.00
Check Condition-Based Service menu for overdue or upcoming services, note due date/remaining mileage. Measure brakes if <5000 miles remaining. Vehicle check 3/28 or 9k Oil & filter - reset Brake fluid flush 7/25 F brakes 32k R brakes 25k							
LABOR: Check & top up engine compartment fluid levels.							0.00
82	Washer fluid, liters					4.00	11.56
82-14-1-467-704	Antifreeze BMW, gallons					0.20	6.09
113307	12/10/2024	191,433	NG	12/11/2024		Total:	1,076.53
Front brakes worn warning LABOR: Inspect brake condition: front worn, rear good (pads at 10mm)							0.00
LABOR: Remove and replace front brake pads, rotors & wear sensor.							1.50 300.00
34-11-6-852-253	Pad set E70					1.00	243.52
34-11-6-886-477	Brake rotor E70/71					2.00	420.52
34-35-6-792-567	Sensor brake wear E70 fro					1.00	40.30
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system. Front 32psi Rear 36psi							0.00
Loaner car LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO7, and agrees to terms of Loaner Car Agreement as shown on reverse.							0.00
113070	11/19/2024	189,818	NG	11/20/2024		Total:	1,823.65
"Service Engine Soon" light on a few days ago, some hissing noise being heard during acceleration LABOR: Perform Short Test of all control module fault memories DDE 4952: pressure control SCR - overpressure fault, delivery module DDE 46F2: DeNox system - function							1.00 80.00
LABOR: Run test module for SCR system: SCR passes tests at this time. Urea quality OK. SCR transfer pump pressure OK. Delivery pump pressures OK.							1.00 1.00 240.00
SCR delivery unit LABOR: Remove & replace failing SCR delivery unit. Reset SCR delivery adaptations. Clear fault codes.							3.00 720.00
16-19-7-244-137	SCR delivery unit					1.00	706.71
07-14-2-151-750	Rivet E70-72					3.00	4.08
Check tire pressures. Adjust to recommended pressures.							

Vehicle Labor and Part History

Bavarian Professionals, Inc.

MH 5/08/2025

Customer: Julian Dodd

Vehicle: 2011 BMW X5 35dX L6 3.0L, 2993cc, DOHC, DIESEL, FI

VIN: L657809

Unit/Fleet Num:

Phone: 415-756-3981

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
	LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.						0.00
	Front 32psi						
	Rear 36psi						

Loaner car

LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO6, and agrees to terms of Loaner Car Agreement as shown on reverse.

0.00

112349	9/19/2024	186,708	MH	9/20/2024		Total:	1,919.87
---------------	-----------	---------	----	-----------	--	---------------	-----------------

Replace front tires in Fall 2024

LABOR: Dismount tire, mount replacement tire & balance. RF wheel is cracked - replace.

2.00 100.00

BRID 255-55-18 Tire Bridgestone Dueler H

2.00 617.52

FREIGHT Shipping & Handling

1.00 40.00

36-11-6-770-200 Wheel 8.5x18" E70 #209

1.00 391.00

LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.

0.00

Front 32psi

Rear 36psi

Check Condition-Based Service menu for overdue or upcoming services, note due date/remaining mileage. Measure brakes if <5000 miles remaining.

Vehicle check 3/28 or 16k

Oil & filter - reset

Brake fluid flush 7/25

F brakes 10k

R brakes 33k

Oil & filter change

LABOR: Drain & replace engine oil, remove & replace oil filter. Reset CBS.

0.75 150.00

83-21-5-A2A-F87 Oil BMW 5W30 diesel, lite

7.50 112.95

11-42-7-788-460 Oil filter kit M57

1.00 23.87

83-19-0-440-158 QT Exhaust fluid diesel, qua

11.00 44.55

LABOR: Check & top up engine compartment fluid levels.

0.00

82 Washer fluid, liters

4.50 13.01

82-14-1-467-704 Antifreeze BMW, gallons

1.00 30.42

4-wheel alignment needed

LABOR: 4-wheel alignment.

1.00 1.00 250.00

Loaner car

LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO6, and agrees to terms of Loaner Car Agreement as shown on reverse.

0.00

111986	8/20/2024	185,022	MH	8/22/2024		Total:	1,971.58
---------------	-----------	---------	----	-----------	--	---------------	-----------------

"Check Engine" light is on

LABOR: Perform Short Test of all control module fault memories

1.00 80.00

4A5E/Glow plug, cylinder 2, activation

Vehicle history for the past 15 months.

Vehicle Labor and Part History

Bavarian Professionals, Inc.

MH 5/08/2025

Customer: Julian Dodd

Vehicle: 2011 BMW X5 35dX L6 3.0L, 2993cc, DOHC, DIESEL, FI

VIN: L657809

Unit/Fleet Num:

Phone: 415-756-3981

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
LABOR: Run test module for fault 4A5E: check lines and plug connections. Recommend replacement of glow plugs and pre-heat control unit as a preventive measure (installed 2019)							
					1.00	0.50	100.00
LABOR: Remove & replace all 6 glow plugs. Clear DDE fault memory.							2.50 500.00
	12-23-7-807-277		Glow plug M57			6.00	541.68
	11-61-2-246-945		Seal intake manifold M57			6.00	71.34
	11-61-7-790-198		Seal intake manifold M57			6.00	71.34
LABOR: Remove and replace glow plug preheat module. Clear fault codes, test drive.							1.50 300.00
	12-21-8-591-724		Module preheat control gl			1.00	303.92
Check tire pressures. Adjust to recommended pressures.							
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.							0.00
Front 32psi							
Rear 36psi							
Check Condition-Based Service menu for overdue or upcoming services, note due date/remaining mileage. Measure brakes if <5000 miles remaining.							
Vehicle check 18000 or 3/28							
Oil & filter 2400 or 3/26							
Brake fluid flush 7/25							
F brakes 12k							
R brakes 35k							
Loaner car							
LABOR: Customer in Bavarian Professionals courtesy loaner car BVPR 11, and agrees to terms of Loaner Car Agreement as shown on reverse.							0.00
111091	6/07/2024	180,884	EI	6/07/2024		Total:	1,247.78
Rear brakes worn							
LABOR: Remove and replace rear brake pads, rotors & wear sensor.					1.50	1.50	300.00
	34-21-6-886-479		Brake rotor E70/71			2.00	362.78
	34-21-6-776-937		Pad set E70/71			1.00	144.67
	34-35-6-854-168		Sensor brake wear E70-72			1.00	33.93
Oil & filter change							
LABOR: Drain & replace engine oil, remove & replace oil filter. Top up diesel exhaust fluid, note quantity used.						0.75	150.00
	83-21-5-A2A-F87		Oil BMW 5W30 diesel, lite			7.50	112.95
	11-42-7-788-460		Oil filter kit M57			1.00	23.27
	83-19-0-440-158QT		Exhaust fluid diesel, qua			8.00	32.40
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.							0.00
Front 32psi							
Rear 36psi							
LABOR: Check & top up engine compartment fluid levels.							0.00
	82		Washer fluid, liters			4.00	11.56
Loaner car							
LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO1, and agrees to terms of loaner car agreement as shown on reverse.							0.00

Vehicle history for the past 15 months.

Vehicle Labor and Part History

Bavarian Professionals, Inc.

MH 5/08/2025

Customer: Julian Dodd

Vehicle: 2011 BMW X5 35dX L6 3.0L, 2993cc, DOHC, DIESEL, FI

VIN: L657809

Unit/Fleet Num:

Phone: 415-756-3981

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
110927	5/23/2024	179,400	NG	5/23/2024		Total:	16.90
Oil level low indicator/message							
LABOR: Check engine oil level. Top up.							0.00
83-21-5-A2A-F87	Oil BMW 5W30 diesel, lite					1.00	15.06
110564	4/23/2024	177,690	MH	4/24/2024		Total:	780.00
Fuel system & PM filter monitors not set							
LABOR: Perform Short Test of all control module fault memories						1.00	80.00
46F2/DDE: DeNOx system, function: 2x, ncp							
480A/DDE: particulate filter system							
LABOR: Compare temperature sensor values at operating temperature: all in spec. Test drive as per OBD-II guidelines to reset DME readiness monitors, all monitors are set.					0.75	3.50	700.00
Check tire pressures. Adjust to recommended pressures.							
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.							0.00
Front 32psi							
Rear 36psi							
Loaner car							
LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO3, and agrees to terms of Loaner Car Agreement as shown on reverse.							0.00
110496	4/16/2024	177,274	MH	4/16/2024		Total:	853.08
Both rear tires need replacement							
LABOR: Dismount tire, mount replacement tire & balance.						2.00	100.00
BRID 255-55-18	Tire Bridgestone DUELER H					2.00	648.96
FREIGHT	Shipping & Handling					1.00	24.10
LABOR: Check & adjust tire pressures. Reset tire pressure monitoring system.							0.00
Front 32psi							
Rear 36psi							
Check Condition-Based Service menu for overdue or upcoming services, note due date/remaining mileage. Measure brakes if <5000 miles remaining.							
Vehicle check 3/28 or 26k							
Oil & filter 3/26 or 11k							
Brake fluid flush 7/25							
F brakes 20k							
R brakes 14k							
Check OBD monitors							
LABOR: PM filter monitoring and fuel system monitoring not ready							0.00
110277	3/29/2024	176,335	MH	3/29/2024		Total:	2,940.53
Oil & filter change							
LABOR: Drain & replace engine oil, remove & replace oil filter. Reset CBS						0.75	150.00

Vehicle history for the past 15 months.

Vehicle Labor and Part History

Bavarian Professionals, Inc.

MH 5/08/2025

Customer: Julian Dodd

Vehicle: 2011 BMW X5 35dX L6 3.0L, 2993cc, DOHC, DIESEL, FI

VIN: L657809

Unit/Fleet Num:

Phone: 415-756-3981

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
83-21-5-A2A-F87	Oil BMW 5W30 diesel, lite					7.50	112.95
11-42-7-788-460	Oil filter kit M57					1.00	23.27
83-19-0-440-158 QT	Exhaust fluid diesel, qua					11.00	44.55
Vehicle Check needed							
LABOR: Perform Vehicle Check as per BMW recommendations. Replace air filter, top up fluids. Reset CBS.						2.00	400.00
13-71-7-798-342	Air filter M57 E70					1.00	83.57
82	Washer fluid, liters					3.00	8.67
LABOR: Remove & replace fuel filter. Perform bleed procedure via ISTA.					0.50	1.25	250.00
13-32-7-822-499	Fuel filter M57/N57					1.00	75.00
07-14-7-129-160	Screw 4.8x15 hex w/washer					4.00	3.76
Foglight out?							
LABOR: Check all exterior lights: ok							0.00
Loaner car							
LABOR: Customer in Bavarian Professionals courtesy loaner car BAVPRO4, and agrees to terms of Loaner Car Agreement as shown on reverse.							0.00
RF lower control arm NR							
LABOR: Remove & replace right front lower control arm.						1.50	300.00
31-12-6-771-894	Control arm E70 RF lower					1.00	460.09
33-30-6-787-062	Nut 14x1.5mm combination					2.00	11.66
31-12-6-780-480	Nut 14mm combination					1.00	12.33
Suspension bushings need replacement							
LABOR: Remove & install upper control arms, press out bushings and replace						2.50	500.00
31-10-6-778-015	Bushing upper c/arm E70					2.00	251.72
Mouse blocker							
LABOR: Remove & replace mouse blocker						0.20	40.00
MOUSEBLOCKER	Mouseblocker					1.00	90.00
109997	3/06/2024	175,162	MH	3/06/2024		Total:	150.00
Water spilled in trunk							
LABOR: Remove & install trunk covers, evacuate water.						0.75	150.00