Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Fime: 09/21/2023 @ 12:51 PM

Model Year:

2012

Vehicle Make: TOYOTA Vehicle Model:

PRIUS C

VIN (manually entered or from DMV document): JTDKDTB33C1027844

License State:

CA

Fuel Type:

Hybrid engine (gas/electric)

License Plate: P927B0 Certification Type: California

Odometer:

96747

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: TO251019C

DMV ID Number: 4241O080T814

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance. Please keep this copy for your records.

The Bureau of Automotive Repair helps consumers with Smog Check repairs, vehicle retirement, collision repair inspections, and more. www.bar.ca.gov

Visual Inspection Result Information

Result	Inspection Category	Result	Inspection Category
NOT APPLICABLE	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
PASS	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOT APPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

Result PASS

Liquid Fuel Leak Check

Result PASS

OBDII

Smog Check Inspection Station Information

Station ID: **SMOGSTERS** TC297484

10791 SAN PABLO AVE

EL CERRITO, CA 94530

(510) 559-3332

Inspector Name/ID: Software Version/OIS ID:

HENNION, MICHAEL/E0111497

23.1.1665.0/CV018041

I certify, under penalty of perjury, under the laws of the State of California that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection eport is true and accurate

Inspector's Signature