



Tel: (510) 693-9687  
 Email: safebuyinc@yahoo.com  
 www.safebuyinc.com

## MULTI POINT VEHICLE INSPECTION CHECKLIST

Customer's Name Buggy Bank	Vehicle model: 2013 Ford C-Max
VIN: DL513137	Mileage: 99888

■ Satisfactory    
 ■ May Require Future Attention    
 ■ Requires Immediate Attention

### Interior / Exterior

Headlights (check high and low beams)/ taillights/ Hazard warning lights/ Turn signal	X		
Interior lights	X		
Windshield washer spray/ Wipers/ blades/	X		
Parking Brakes	X		
Horn Operation	X		
Clutch Operation (If applicable)			
A/C & Heater	X		
Windows operation (Up, Down)	X		

### Battery / Charging System

Good	X		
Replace			



### Under Hood

Check fluid levels: Oil/Coolant/ Power steering/ Brake fluid/ Windshield washer fluid/ Automatic transmission fluid	X		
Air filter condition	X		
External drive belts and radiator hoses	X		
Hydraulic clutch reservoir fluid (M/T Vehicles)			

### Under Vehicles

Brake lines/ Hoses/ Parking brake cable	X		
Shock absorbers/ Struts/ Suspension/ Tie rods and boots	X		
Dust Seals	X		
Exhaust System	X		
Engine oil and/ or fluid leaks	X		
Driveshaft Boots	X		

### Brakes

Left Front	X		
Right Front	X		

Left Rear	X		
Right Rear	X		

### Tires

Left Front	X	X	Right Front
Left Rear	X	X	Right Rear

Comments:

---

---

---


---

---

External Damage



Spare Tire: Yes/No



Wheel Jack: Y



## 2013 MY(Model Year) Ford VEHICLE DIAGNOSTIC REPORT

### Vehicle Information

2013 MY(Model Year)/Ford/C-MAX/  
 VIN: 1FADP5BU9DL513137

Odometer Reading: 160722.7km  
 License Plate: --

### Customer Information

Name: --

Tel: --

### Device information

Scanner: MaxiSys MS906  
 Version: V8.70

Serial Number: D58G60107362  
 Repair Order Number: --

### System Scanned( 25 )

System	Status/DTC
PCM (Powertrain Control Module)	✔ 0
ABS (Anti-lock Brake System)	✔ 0
RCM (Restraint Control Module)	✔ 0
OCSM (Occupant Classification System Module)	✔ 0
IPC (Instrument Panel Control Module)	✔ 0
ACCM (Air Conditioning Control Module)	✔ 0
ACM (Audio Control Module)	✔ 0
APIM (Accessory Protocol Interface Module)	✔ 0
BECM (Battery Energy Control Module)	✔ 0
BdyCM(Body control module)	✔ 0
DACM-C (Digital Audio Control Module C)	✔ 0
DCDC (DC/DC Converter Control Module)	✔ 0
DDM (Driver Door Module)	✔ 0
FCIM (Front Controls Interface Module)	✔ 0
GPSM (Global Positioning System Module)	✔ 0
GWM (Gateway Module A)	✔ 0
HVAC (Heating Ventilation Air Conditioning)	✔ 0
IPM-B (Image Processing Module B)	✔ 0

2013 MY(Model Year)/Ford/C-MAX/

Test Time: 2025-01-12 21:57:57

Report ID: MAXIA20250112215757

PAM (Parking Aid Module)	✔ 0
PDM (Passenger Door Module)	✔ 0
PSCM (Power Steering Control Module)	✔ 0
RFA (Remote Function Actuator)	✔ 0
RGTM (Rear Gate/Trunk Module)	✔ 0
SASM (Steering Angle Sensor Module)	✔ 0
SOBDM-C (Secondary OBD Control Module C)	✔ 0

### DTC ( 0 )

### Technician Notes