

2013 Chevrolet VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2013/Chevrolet/Volt/
 VIN: 1G1RH6E46DU119483

Odometer Reading: --
 License Plate: --

Customer Information

Name: --



















Tel: --

Device information











Scanner: MaxiSys MS906
 Version: V26.00

Serial Number: DS8G60107362
 Repair Order Number: --

System Scanned(28)

System	Status/DTC
Engine control module	 0
Transmission control module	 0
Electronic brake control module	 0
Inflatable restraint sensing and diagnostic module	 0
Instrument cluster	 0
Parking brake control module	 0
Drive motor control module 1	 0
Drive motor control module 2	 0
Hybrid powertrain control module	 0
Hybrid powertrain control module 2	 0
Power steering control module	 0
Steering wheel angle sensor module	 0
Fuel pump control module	 0
Parking assist control module	 0
Auxiliary transmission fluid pump	 0
Battery charger control module	 0
Battery energy control module	 0
Body control module	 0

2013/Chevrolet/Volt/	Test Time: 2025-01-12 21:05:37	Report ID: MAXIA20250112210537
----------------------	--------------------------------	--------------------------------

Coolant heater control module	 0
Electric A/C compressor control module	 0
Front seat heating control module	 0
Frontview camera module	 0
HVAC control module	 0
Keyless entry control module	 0
Multi-axis acceleration sensor module	 0
Passenger presence module	 0
Radio	 0
Telematics communication interface control module	 0

DTC (0)

Technician Notes



MULTI POINT VEHICLE INSPECTION CHECKLIST

Tel: (510) 693-9687
 Email: safebuyinc@yahoo.com
 www.safebuyinc.com

Customer's Name Buggy Bank	Vehicle model: 2013 Chevy Volt
VIN: DU119483	Mileage: 86163

■ Satisfactory
 ■ May Require Future Attention
 ■ Requires Immediate Attention

Interior / Exterior

Headlights (check high and low beams)/ taillights/ Hazard warning lights/ Turn signal	X		
Interior lights	X		
Windshield washer spray/ Wipers/ blades/	X		
Parking Brakes	X		
Horn Operation	X		
Clutch Operation (If applicable)			
A/C & Heater	X		
Windows operation (Up, Down)	X		

Battery / Charging System

Good	X	
Replace		



Under Hood

Check fluid levels: Oil/Coolant/ Power steering/ Brake fluid/ Windshield washer fluid/ Automatic transmission fluid	X		
Air filter condition	X		
External drive belts and radiator hoses	X		
Hydraulic clutch reservoir fluid (M/T Vehicles)	X		

Under Vehicles

Brake lines/ Hoses/ Parking brake cable	X		
Shock absorbers/ Struts/ Suspension/ Tie rods and boots	X		
Dust Seals	X		
Exhaust System	X		
Engine oil and/ or fluid leaks	X		
Driveshaft Boots	X		

Brakes

Left Front	X		
Right Front	X		

Left Rear	X		
Right Rear	X		

Tires

Left Front	X	X	Right Front
Left Rear	X	X	Right Rear

Comments:


* Signs of an oil leak under the exhaust Manifold. Recommend further diagnosis.

External Damage



Spare Tire: Yes **No**

Repair Kit



Wheel Jack: Yes/No