

OAKLAND



CHEVROLET

2735 Broadway
Oakland, CA 94612
Phone: 510-398-1200
www.oaklandchevrolet.com

7000747

INVOICE

DUPLICATE 1
PAGE 2

B.A.R. REG.# 304024 EPA# CAL00047118

SERVICE ADVISOR: 4443 JESUS TORRES

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TA, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Includes vehicle details for a 2013 Chevrolet Volt.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes a line for VALVE VALVE.

VALVE VALVE - - -
301 C 973.50 973.50
PARTS: 0.00 LABOR: 973.50 OTHER: 0.00 TOTAL LINE D: 973.50
REPLACED VALVE COVER GASKET. INSPECTED VEHICLE FOR FURTHER LEAKS.
NONE FOUND AT THIS TIME. TECHNICIAN TEST DROVE VEHICLE AND COULD NOT
FIND ANY SIGNS OF VEHICLE SMOKING. NO FURTHER REPAIRS NEEDED AT THIS
TIME

ESTIMATE: 1,268.50 14JAN25 14:00 SA: 4443

CONTACT: [Redacted]

APPROVED VALVE COVER REPLACEMENT

CREATED 2025-01-13 08:47:00AM
TAKEN BY DIANNA NOLAZCO

Table with columns: Original Estimate (Parts & Labor), Total Additional Cost Authorized, Approved By, Date & Time, Authorization Obtained By, *HAZARDOUS WASTE DISPOSAL COSTS, DESCRIPTION, TOTALS. Includes a signature section for the customer and dealership representative.

The vehicle is being returned to you in exchange for your payment of the Amount Due.

NOTICE TO CONSUMER: PLEASE READ IMPORTA
INFORMATION ON BACK.