



Tel: (510) 693-9687  
 Email: safebuyinc@yahoo.com  
 www.safebuyinc.com

## MULTI POINT VEHICLE INSPECTION CHECKLIST

Customer's Name	Vehicle model:
<b>Buggy Bank</b>	<b>2004 Honda Element</b>
VIN:	Mileage:
<b>L016194</b>	<b>226456</b>

■ Satisfactory    
 ■ May Require Future Attention    
 ■ Requires Immediate Attention

### Interior / Exterior

Headlights (check high and low beams)/ taillights/ Hazard warning lights/ Turn signal	✓		
Interior lights	✓		
Windshield washer spray/ Wipers/ blades/		✓	
Parking Brakes	✓		
Horn Operation	✓		
Clutch Operation (If applicable)			
A/C & Heater	✓		
Windows operation (Up, Down)	✓		

### Battery / Charging System

Good	✓
Replace	



### Under Hood

Check fluid levels: Oil/Coolant/ Power steering/ Brake fluid/ Windshield washer fluid/ Automatic transmission fluid	✓		
Air filter condition	✓		
External drive belts and radiator hoses	✓		
Hydraulic clutch reservoir fluid (M/T Vehicles)	✓		

### Under Vehicles

Brake lines/ Hoses/ Parking brake cable	✓		
Shock absorbers/ Struts/ Suspension/ Tie rods and boots		✓	
Dust Seals	✓		
Exhaust System	✓		
Engine oil and/ or fluid leaks			✓
Driveshaft Boots	✓		

### Brakes

Left Front	✓		
Right Front	✓		

Left Rear	✓		
Right Rear	✓		

### Tires

Left Front	✓	✓	Right Front
Left Rear	✓	✓	Right Rear


### Comments:

- \* Oil leak from valve cover
- \* Oil leak from oil pan
- \* Sign of oil leak from timing chain cover
- \*\*\* To pinpoint all leaks, need to clean all the oil under the car, drive the car and re-check
- \* Recommend replacing wiper blades

### External Damage



Spare Tire: **Yes**/No



Wheel Jack: Yes/**No**