Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 03/05/2025 @ 1:23 PM

Model Year:

2006

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

NEW BEETLE 2.5L OPTION

PACKAGE I

VIN (scanned from vehicle):

3VWRG31C26M4I1531

License Plate:

5XAK257

License State:

CA

Fuel Type:

Gasoline

Certification Type: California

Odometer:

84801

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: UK591640C

DMV ID Number: 3029K953U831

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance. Please keep this copy for your records.

The Bureau of Automotive Repair helps consumers with Smog Check repairs, vehicle retirement, collision repair inspections, and more. www.bar.ca.gov

Visual Inspection Result Information

Result	Inspection Category	Result	Inspection Category
PASS	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOT APPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOT APPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

Result

Result

PASS

Liquid Fuel Leak Check

PASS

OBDII

PASS

Smoke Check

Smog Check Inspection Station Information

Station ID:

TC269642

Inspector Name/ID:

KENT, JESSIE/EO630955

BERKELEY SMOG TEST ONLY CENTER

Software Version/OIS ID:

24.4.1830.0/CV015923

2959 san pablo ave BERKELEY, CA 94702

(510) 549-2355

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and occurate.

Inspector's Signature