



Tel: (510) 693-9687
 Email: safebuyinc@yahoo.com
 www.safebuyinc.com

MULTI POINT VEHICLE INSPECTION CHECKLIST

Customer's Name	Vehicle model:
Buggy Bank	2006 VW Beetle
VIN:	Mileage:
M411531	84798

■ Satisfactory
 ■ May Require Future Attention
 ■ Requires Immediate Attention

Interior / Exterior

Headlights (check high and low beams)/ taillights/ Hazard warning lights/ Turn signal	✓	■	■
Interior lights	✓	■	■
Windshield washer spray/ Wipers/ blades/	✓	■	■
Parking Brakes	✓	■	■
Horn Operation	✓	■	■
Clutch Operation (If applicable)	✓	■	■
A/C & Heater	✓	■	■
Windows operation (Up, Down)	✓	■	■

Battery / Charging System

Good	✓	■	■
Replace	■	■	■



Under Hood

Check fluid levels: Oil/Coolant/ Power steering/ Brake fluid/ Windshield washer fluid/ Automatic transmission fluid	✓	■	■
Air filter condition	✓	■	■
External drive belts and radiator hoses	✓	■	■
Hydraulic clutch reservoir fluid (M/T Vehicles)	✓	■	■

Under Vehicles

Brake lines/ Hoses/ Parking brake cable	✓	■	■
Shock absorbers/ Struts/ Suspension/ Tie rods and boots	✓	■	■
Dust Seals	✓	■	■
Exhaust System	✓	■	■
Engine oil and/ or fluid leaks	✓	■	■
Driveshaft Boots	✓	■	■

Brakes

Left Front	✓	■	■
Right Front	✓	■	■

Left Rear	✓	■	■
Right Rear	✓	■	■


Tires

Left Front	✓	■	■	Right Front
Left Rear	✓	■	■	Right Rear


Comments:

* Oil leak from oil pan

External Damage



Spare Tire: **YES** / NO



Wheel Jack: **YES** / NO