



Art's Automotive
2871 San Pablo Ave
Berkeley, CA 94702
BAR: ARD0008014
EPA: 000000100
(510) 540-7093
everyone@artsautomotive.com

Invoice #15754
Page 3 of 3
11/07/2024 5:26 PM

INSPECTION REPORT

Full Vehicle Inspection

<input checked="" type="checkbox"/>	Road test
<input checked="" type="checkbox"/>	Climate control
<input checked="" type="checkbox"/>	Parking brake
<input checked="" type="checkbox"/>	Wipers
<input checked="" type="checkbox"/>	Lights
<input checked="" type="checkbox"/>	Fluids: Transmission fluid is fairly dark. Brake fluid look OK but is likely due for preventive service. Other fluids look OK today. Consider transmission and brake fluid service
<input checked="" type="checkbox"/>	Filters
<input checked="" type="checkbox"/>	Battery
<input checked="" type="checkbox"/>	Drive belts
<input checked="" type="checkbox"/>	Hoses
<input checked="" type="checkbox"/>	Tires (including spare): Front tires are at/near the wear bars. Rear tires have about 5mm tread. They are all dated 2018. Recommend replacing at least 2 tires now or soon. P195/65R15
<input checked="" type="checkbox"/>	Front brake pads 6mm
<input checked="" type="checkbox"/>	Rear brake shoes 3mm
<input checked="" type="checkbox"/>	Driveline
<input checked="" type="checkbox"/>	Exhaust
<input checked="" type="checkbox"/>	Steering / Suspension: Both front axles are new (aftermarket). There is minor wetness at the RF axle seal, but it does not look like active leakage. Should be monitored
<input checked="" type="checkbox"/>	Fluid leaks: Minor oil leakage at timing cover/timing chain tensioner cap area. Common on this engine and OK to monitor at this time
<input checked="" type="checkbox"/>	Glovebox damper is missing

What to Expect:

If you have not scheduled installation, please call or stop by the store. Walk-ins are welcome! When you arrive, please be ready to present your vehicle's physical key and your (or Alternate Pick-Up's) ID.




We'll check you in and confirm your wait time.



We'll contact you when your service is completed.

MY ORDER

 2010 Toyota Corolla Base 195 /65 R15 SL

TIRES



Falken

**Sincera SN250
A/S**

P 195 /65 R15 91H SL BSW

\$93.00/ea

Qty: 2

Price: \$186.00

Item #26725

★★★★★ 4.8

0 In Stock

✓ Available as soon as Thursday,
Jan. 30 at My Store

 MY STORE

1350 PINE ST

Walnut Creek, CA 94596-3629

FEES	EACH	QTY	PRICE
Tire Disposal Fee	\$3.50	2	\$7.00
Environmental Fee	\$1.75	2	\$3.50