

Multi-Point Inspection Form

RO# 661515

VIN 3FTTW8F94PRA97830

Advisor TIMOTHY CORNOLLY

Technician Iver Ochoa

Created On 4/23/2025

☒ Checked and OK at this time☐ May Require Future Attention☐ Requires immediate attention

Interior / Exterior

- | | | |
|-------------------------------------|--------------------------|---|
| ☒ | ☐ | Bulbs and Lights |
| ☒ | ☐ | Windshield Washer Spray / Wiper Operation / Wiper Blades / Including Rear (if applicable) |
| ☒ | ☐ | Windshield / Window Condition |
| ☒ | ☐ | Upholstery / Carpet / Floor Mats / Mirrors / Trim |
| ☒ | ☐ | Emergency Brake Adjustment |
| ☒ | ☐ | Horn Operation |
| ☒ | ☐ | Fuel Tank Cap Gasket |
| ☒ | ☐ | Clutch Operation (if equipped) |
| ☒ | ☐ | Cabin/HEPA Filter (if equipped) |

Battery Performance

- | | | |
|-------------------------------------|--------------------------|--|
| ☒ | ☐ | Battery Terminals / Cables / Mountings |
| ☒ | ☐ | Check Condition of Battery (Storage Capacity Test if Applicable) |

Under Hood

- | | | |
|-------------------------------------|--------------------------|--|
| ☒ | ☐ | Fluids: Oil / Coolant / Power Steering / Brake Fluid / Washer |
| ☒ | ☐ | Engine Air Filter |
| ☒ | ☐ | Belts / Tensioners (condition and adjustment) |
| ☒ | ☐ | Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections |
| ☒ | ☐ | Radiator Core / Air Conditioning Condenser (if equipped) |

Under Vehicle

- | | | |
|-------------------------------------|--------------------------|--|
| ☒ | ☐ | Shock Absorbers / Suspension |
| ☒ | ☐ | Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers |
| ☒ | ☐ | Muffler / Exhaust Pipes / Mountings |
| ☒ | ☐ | Engine Oil and/or Fluid Leaks |
| ☒ | ☐ | Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped) |
| ☒ | ☐ | Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks) |
| ☒ | ☐ | Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses |
| ☒ | ☐ | Inspect Nuts and Bolts on Body Chassis |

Tread Depth (measured in 1/32")



- | | | |
|-------------------------------------|--------------------------|----------------------------|
| ☒ | ☐ | LF 2 |
| ☒ | ☐ | RF 2 |
| ☒ | ☐ | LR 2 |
| ☒ | ☐ | RR 2 |
| ☒ | ☐ | Spare Tire (if applicable) |
| ☒ | ☐ | LF/RF Tire Pressure 35 |
| ☒ | ☐ | LR/RR Tire Pressure 35 |

Abnormal Wear Pattern of Tires

- | | | |
|-------------------------------------|--------------------------|----|
| ☒ | ☐ | LF |
| ☒ | ☐ | RF |
| ☒ | ☐ | LR |
| ☒ | ☐ | RR |

Check Brake Linings (measured in millimeters)

- | | | |
|-------------------------------------|--------------------------|-------|
| ☒ | ☐ | LF 10 |
| ☒ | ☐ | RF 10 |
| ☒ | ☐ | LR 8 |
| ☒ | ☐ | RR 8 |

Prepared By jcxtime