

## MULTI-POINT INSPECTION FORM

USTOMER AND VEHICLE INFORMATION			VEHICLE INFORMATION	VEHICLE CONDITION		CONDITION	SERVICE INFORMATION
ate: 4/18/2025 Time In:					5	E	Description of service to be performed:
ustomer Name: RICH GRAFF							
ddress: 4420 NORTON AVE OAKLAND CA 94602							
oday's Contact Phone #: <b>5105527447</b>							Initial Estimate:
mail: rich.graff440@gmail.com							I hereby authorize the repair work and inspection described to be performed along with the necessary materials and agree that deal
	ear/Make/Model: 2021 TT RAV4						not responsible for loss or damage to vehicle or articles left in vehicase of fire, theft, or any cause beyond their control. I hereby gran
							and/or your employees permission to operate the vehicle as neces for testing and inspection purposes.
-	ge: <b>48</b> 7		License #: IVG2713				Customer decline access to spare tire
IN:JTMM6RFV6MD015916							Customer decline access to glove box
4 T	ime:		Promise Time: 17:00:00 HAT/Tag #: 2102				Signature:
٦	<b>V</b>		Horn operation			Factory Specs (P.	S.I.) FRSpare
ō	<b>V</b>		Head lights / tail lights / turn signals / brake lights / hazard warn lights / exterior lamps (check for damage and operation)	ing		Tire pressure P.S.	I. checked/adjusted to
Exterior	1		Windshield wiper and washer operation			LF / RF / LR / RR / Spare / Spare not checked/adjusted  Tread Depth:  LF /32 RF /32 LR /32 RR /32	
	<b>√</b>		Windshield glass				
		Ш	Fuel tank cap gasket				
٦	<b>V</b>		Dome light / amp light / dimmer combination meter	<u>se</u>	Tires		
Interior	V	į.	Cabin air filter	-		Tire damage / abnormal wear:	
Inte	<b>V</b>		Parking brake operation		-   '	LF RF LR RR Spare	
	<b>V</b>		Check for proper installation of driver floor mat (if equipped)		- I		
٦	1		Air filter			Rims/wheels/lug nuts:  LF RF LR RR	
	V		Battery condition (cables / clamps / corrosion)				
pool	<b>V</b>		Battery state of health			Tires Rotated Torque Spec:	
Under Hood	<b>√</b>		Cooling system (leaks)			Brake Lining:	
5	$ \mathbf{A} $	Ш	Hoses (cracks / damage / leaks)			LFmm RFmm LRmm RRmm	
		Н	Drive belts (cracks / damage / wear)				Farat//Dava
_		Ш	Radiator core / air condition condenser (if equipped)		kes		Front/Rear Disc Brakes
		Filled		Bra	Brakes		12-7 mm 5-4 mm 3-0 mm
	V		Windshield Washer				Rear Drum Brakes
	Y/	H	Coolant ( degree of protection)  Power steering (if equipped)				4-3 mm 2 mm 1-0 mm
Fluids		H	Brake reservoir			<b>√</b> Brak	ke Lines / hoses / parking brake cable
Ē			Clutch reservoir (if equipped)			3	
	1	П	Transmission / transaxle	Com	Comm	nents:	
	<b>√</b>		Differential (if equipped)	_			
		~	Transfer case (4WD models/if equipped)	T	Techn	ician Team:	
$\neg$	T	П	Propeller / driveshaft (damage / leaks / U-joints) (if equipped)		Printed on: 5/29/2025		
	1		Drive / CV shaft (damage / leaks / boots)				
e e	1		Axle hub & bearing (damage / leaks / noise)				
Under Vehicle	1		Steering linkage (damage / leaks / worn components)				
nder	<b>V</b>		Suspension (damage / leaks / worn components)				
5	1		Fluid leaks (engine / transmission / differential)				
	<b>V</b>		Exhaust system (damage / leaks / corrosion)				
Ш	1		Fuel lines & connections / fuel tank bands / fuel tank vapor vent system hoses (damage / leaks / corrosion)	t			