

MULTI-POINT INSPECTION REPORT

☒ CHECKED & OKAY ☐ WILL REQUIRE FUTURE ATTENTION ☐ REQUIRES IMMEDIATE ATTENTION


☒ May contribute to vehicle efficiency and a green environment ☐ Maintenance/Wear Item

Name: [REDACTED] Date: 05/30/2025
 E-mail address on file? ☐ Yes ☐ No E-mail address: [REDACTED] State inspection month:
 OK to text when ready? ☐ Yes ☐ No Phone number: [REDACTED] Mileage: 71327
 Model/Year: HYUNDAI ELANTRA 2012 VIN: KMHDH4AE3CU432215 RO / Hat #: 393354
 Waiting? ☐ Yes ☐ No WebDCS Open Campaigns checked? ☐ Yes ☐ No Promise time:
 BlueLink enrolled: ☐ Yes ☐ No ☐ N/A Subscription: ☐ Connected Care ☐ Remote ☐ Guidance

INSPECTION POINTS

EXTERIOR	☒ Head Lights / Fog Lights / Turn Signals ☒ Tail Lights / Brake Lights / License Plate Light ☒ Windshield (cracks, chips and pitting) ☒ Wiper Blades - Condition, operation
INTERIOR	☒ Cabin Air Filter ☒ Horn (operation) / Interior Lights ☒ Heat / A/C System (operation)
BATTERY	☒ Battery Terminals (Clean, if necessary) ☒ Battery Performance Attach Battery test results
UNDER HOOD	☒ Engine Air Filter ☒ Cooling System (check for visible leaks and damage) ☒ Radiator, Heater, A/C hoses ☒ Drive Belts
FLUID LEVELS	☒ OK ☐ FILL ☒ Engine Oil Level - On arrival ☒ Transaxle / Transmission (if equipped with dipstick) ☒ Coolant (level / condition) ☒ Brake Fluid (level / condition) If low, check pad wear ☒ Power Steering Fluid (may be N/A) ☒ Windshield Washer Fluid
UNDER CAR	☒ Drive Shaft Boots / Constant Velocity Boots (as equipped) ☒ Shocks, Struts and Suspension components ☒ Steering, linkages / wheel end play / bearings ☒ Transaxle, Transfer case, Driveshaft ☒ Transmission, U-joints, Shift Linkage ☒ Exhaust system (leaks, visible damage, loose parts, corrosion) ☒ Oil and / or fluid leaks, visual inspection (Specify) ☒ Brake lines, hoses, parking brake

RECEPTION INSPECTION AND WALK-AROUND



TIRES & BRAKES

LEFT FRONT	Tire Age: 32 PSI set to Factory Spec: 32 Tire tread depth: 9 Brake Lining: N/C	RIGHT FRONT	Tire Age: 32 PSI set to Factory Spec: 32 Tire tread depth: 9 Brake Lining: N/C
LEFT REAR	Tire Age: 32 PSI set to Factory Spec: 32 Tire tread depth: 9 Brake Lining: N/C	RIGHT REAR	Tire Age: 32 PSI set to Factory Spec: 32 Tire tread depth: 9 Brake Lining: N/C
Tire Age: _____ PSI set to Factory Spec: N/A Uneven Tire wear? ☒ NO ☐ YES If YES, we recommend: ☒ Improper inflation, check inflation pressure monthly ☐ Alignment check recommended ☐ Tire Replacement ☒ Brake measurements not taken this service visit Tire Age: Any tires that are over six (6) years old based on the manufacturing date should be replaced by new ones. See Owner's manual for additional information.			

TIRE AND BRAKE MEASUREMENT REFERENCE

TIRES	BRAKE PADS	BRAKE SHOES

Comments:

Technician Name and/or Signature: NUNEZ-PACHECO, SERGIO, Sergio Consultant Name: JAYSON WALLACE

Customer Signature:

DISTRIBUTION: PART 1 - CUSTOMER COPY PART 2 - DEALER COPY

Your Road Service Appointment is: Date: Time: