



INSPECTION CHECK LIST

Name: TREVOR Year/Model: 2007 IS 250 Date: 06/20/25


Repair Order #: _____ VIN (last 8 digits): 72030943 Odometer: 101699 Phone #: _____

☐ Checked and OK

☐ May Need Attention Soon

☐ Needs Immediate Attention

WIPER BLADES



TIRES AND TREAD DEPTH

(Check Body Condition)

Left Front: PSI @: 35 PSI Set to: 35 PSI

Left Rear: PSI @: 35 PSI Set to: 35 PSI

Right Front: PSI @: 35 PSI Set to: 35 PSI

Right Rear: PSI @: 35 PSI Set to: 35 PSI

(Check Lamps)

☒ ☒ Tire Pressure Monitoring System

☐ Rotation Needed ☐ Alignment Needed ☐ Balance Needed

☐ Rotation Performed ☐ Alignment Performed ☐ Balance Performed

LF ☐ LR ☐ RF ☐ RR ☐

Wear Pattern/Damage

BATTERY



FLUID LEVELS

OK FILLED REQUIRES ATTENTION

☒ Engine Oil ☐

☒ Brake Fluid Reservoir ☐

☒ Transmission (if equipped w/dipstick) ☐

☒ Coolant Recovery Reservoir ☐

☒ Power Steering ☐

☒ Windshield Washer ☐

BRAKES

☒ Brake Noise ☐ Brake Hoses

☒ Excessive Dust ☐ Rear Linings

☒ Front Linings ☐ Steel Line Condition

8mm 1mm pads

☒ Parking Brake

INTERIOR

☒ AC ☒ Lighting ☒ Heating

EXTERIOR

☒ Headlights ☒ Brake Lights ☒ Turn Signals

ADDITIONAL INSPECTIONS

Inspect For Visible Leaks:

☒ Fuel System (also including gas cap seating)

☒ Engine, Transmission, Drive Axle, Transfer Case

☒ Engine Cooling System

☒ Shocks and Struts (also check operation)

Inspect Visual Condition:

☒ Belts: Engine, Accessory, Serpentine and/or V-Drive

☒ Hoses: Engine, Power Steering and HVAC

☒ Engine Air Filter and Cabin Air Filter

☒ Steering Components and Steering Linkage

☒ CV Drive Axle Boots and Driveshafts and U-Joints

☒ Exhaust System Components

ADDITIONAL RECOMMENDED SERVICES

1) Front strut oil leak

2) Need Rear brakes pads + rotors

3) Recommend change brake fluid

4) air & cabin filter dirty

5) _____

6) _____

Car Care Center: _____

Technician: PH Phone #: _____

Next Appointment: _____