

Honda Multi Point Vehicle Inspection Checklist



CUSTOMER NAME [REDACTED]	NO TAG NUMBER 281158-202503	NEXT SERVICE DUE
CUSTOMER CONTACT NUMBER [REDACTED]	VIN SHHFK7H21HU412958	MI/AGE 60488
CUSTOMER EMAIL ADDRESS to.nicole.ermoo@gmail.com	SERVICE ADVISOR Matthew Youhana	TECHNICIAN Steven Hoang

☒ Satisfactory
 ☐ May Require Future Attention
 ☐ Requires Immediate Attention

Exterior/Interior

Headlights (check high and low beams) Tailights/Brake lights/Hazard warning lights/Turn signals/Exterior lamps	☒	☐	☐
Interior light	☒	☐	☐
Windshield washer spray/Wiper operation/Wiper blades/Windshield condition	☒	☐	☐
Parking brake	☒	☐	☐
Horn operation	☒	☐	☐
Clutch operation	☒	☐	☐
Cabin Air Filter	☒	☐	☐
Cabin air filter replaced at owner's manual service interval?	☒	☐	☐

Battery Performance (see attached ED-18 printout)

Good	☒
Replace	☐



Under Hood

Check fluid levels: Oil/Coolant/Power steering fluid/Brake fluid/Windshield washer fluid/Automatic transmission fluid	☒	☐	☐
External drive belts and radiator hoses	☒	☐	☐
Hydraulic clutch reservoir fluid (MT vehicles)	☒	☐	☐
Engine Air Filter	☒	☐	☐
Engine air filter replaced at owner's manual service interval?	☒	☐	☐

Under Vehicle

Brake lines/hoses/Parking brake cable	☒	☐	☐
Shock absorbers/Struts/Suspension/Tie rod ends and boots/Steering gear and ball joints	☒	☐	☐
Exhaust system	☒	☐	☐
Engine oil and/or fluid leaks	☒	☐	☐
Drive shaft boots/Constant velocity boots and bands	☒	☐	☐

Comments

--

Tire Condition

Left Front	Right Front
Wear Pattern	Wear Pattern
Tire tread 6 - 32nds	Tire tread 6 - 32nds
Left Rear	Right Rear
Wear Pattern	Wear Pattern
Tire tread 6 - 32nds	Tire tread 6 - 32nds
Spare	Front tire inflation set to 32 psi
Wear Pattern	Rear tire inflation set to 32 psi
Tire tread 6 - 32nds	

Brake Condition

Left Front	Right Front
7 mm	7 mm
Left Rear	Right Rear
7 mm	7 mm
Brake not inspected on this visit ☐	

Please Indicate Areas of External Damage or Wear

*Note: Brake fluid NOT bleed - fluid level indicates pad wear