

Oakland Acura Multipoint Inspection

Customer Name: STEPHEN MICHAEL GREENWA Vehicle Year/Model: 23 ACURA INTEGRA

Phone: (H) (732) 406-4968

VIN: 19UDE4G74PA002238

Printed: 06/27/2025 10:12:37

Odometer: 16946

Service Advisor: MATTHEW PENCE

Technician: BRYAN CERVANTES RODRIGUEZ

RO: 329860

Tag: 871W

INSPECTION RESULT - OK

WILL REQUIRE FURTHER ATTENTION

REQUIRES IMMEDIATE ATTENTION

Green Yellow Red

Service

☒	☐	Fill windshield washer fluid	☐
☒	☐	Inspect wipers/washers including front and rear blades	☐
☒	☐	Inspect exterior lamps/lights/bulbs (operation/damage)	☐
☒	☐	Warning lights	☐
☒	☐	Inspect dash lights/interior lights/horn operation	☐
☒	☐	Interior	☐
☒	☐	Inspect air cleaner element	☒
☒	☐	Inspect cabin air filter (if equipped)	☒
☒	☐	Inspect drive belts and hoses	☐
☒	☐	Inspect battery terminals and cables	☐
☒	☐	Check brake fluid level and condition	☒
☒	☐	Check engine coolant level and condition	☐
☒	☐	Check power steering fluid level and condition	☐
☒	☐	Check transmission fluid level and condition (most models)	☐
☒	☐	Under hood	☐
☒	☐	Inspect front/rear differential and transfer case (leaks)	☐
☒	☐	Inspect exhaust system (leaks/damage/loose parts)	☐
☒	☐	Inspect brake system components (leaks/wear/damage)	☐
☒	☐	Inspect steering system (leaks/wear/damage)	☐
☒	☐	Inspect cooling system (leaks/wear/damage)	☐
☒	☐	Inspect front suspension	☐
☒	☐	Inspect rear suspension	☐
☒	☐	Inspect axles/driveshaft(s)/U-joints/CV joints/boots	☐
☒	☐	Inspect transmission for leaks	☐
☒	☐	Inspect engine (leaks/wear/damage)	☐
☒	☐	Inspect fuel tank/lines/connections	☐
☒	☐	Time/mileage recommendations	☐
☒	☐	Other Concerns	☐

Brake Lining Measurements: LF: 8 mm RF: 8 mm LR: 6 mm RR: 6 mm

Tire Tread Measurements: LF: 4/32" RF: 7/32" LR: 6/32" RR: 6/32"

Tire Pressure Measurements: LF: 35psi RF: 35psi LR: 35psi RR: 35psi

General Comment: 235/40/R18 CONTINENTAL

Front / Rear Brake Linings

LF	☒ Green	☐ Yellow	☐ Red
RF	☒ Green	☐ Yellow	☐ Red
LR	☒ Green	☐ Yellow	☐ Red
RR	☒ Green	☐ Yellow	☐ Red

☐ Inspection Not Taken

More than 50% remaining

20% to 50% remaining

Less than 20% remaining

Check Tires / Tread Depth

LF	☒ Green	☐ Yellow	☐ Red
RF	☒ Green	☐ Yellow	☐ Red
LR	☒ Green	☐ Yellow	☐ Red
RR	☒ Green	☐ Yellow	☐ Red

Spent: ☐ Green ☐ Yellow ☐ Red

6/32" or Greater

4/32" to 5/32"

3/32" or Less

Check Battery 1 Performance

☒	Good
☐	Fair
☐	Bad
Actual Cold Cranking Amps	684
Factory Cold Cranking Amps	450

Check Battery 2 Performance

☒	Good
☐	Fair
☐	Bad
Actual Cold Cranking Amps	
Factory Cold Cranking Amps	